

Washing Machine Rate Card

Top Load WM - Power Unit

* Repair - inverter PCB top load	= 2000
* Power 3 pin plug top	= 200
* Power cord	= 350
* Replace new - PCB top load (labour)	= 299
* Repair - PCB top load	= 1600

Top Load - Wash Issue

* Capacitor	= 250
* Pressure sensor with pipe	= 850
* Drain cleaning	= 300
* Door lock top load	= 1300
* AC inlet valve 1 way	= 650
* AC inlet valve 2 way	= 850
* AC inlet valve 3/4 way	= 1300
* DC inlet valve 1 way	= 850
* DC inlet valve 2 way	= 1100
* DC inlet valve 3/4 way	= 1800
* Main motor	= 2100
* Hall sensor	= 600
* Direct drive motor	= 3800
* Heater	= 700
* V Belt	= 300

Top Load - Spin Issue

* DC Drain motor	= 1500
* Clutch assembly	= 3800
* AC Drain motor	= 1300

Top Load - Water Leakage

* Inner Drain Hose	= 300
--------------------	-------

- * Drain case assembly DV case assembly = 900
- * Drain case cleaning = 350

Top Load - Accessories

- * Shocker set 4 pieces = 2000
- * Chemical wash = 900
- * Stand trolley = 900
- * Extension inlet pipe 4 meter with adaptor = 500
- * Inlet pipe 1.5 mtr with adaptor = 400
- * Drain pipe = 300
- * Pulsator = 1000
- * Power 3 pin plug top = 200
- * Tap adaptor = 300
- * Washing machine cover = 500
- * Water filter = 1300

Front Load - Power Unit

- * Power 3 pin plug top = 150
- * Power cord = 350
- * Repair inverter PCB (front load) = 2500
- * Repair PCB (front load) = 2000
- * Replace new PCB (front load) (labour) = 299

Front Load - Wash Issue

- * Door lock (front load) = 1300
- * AC inlet valve 3/4 way = 1000
- * DC inlet valve 3/4 way = 1800
- * Door gasket = 2000
- * Complete drum assembly = 6000
- * Capacitor = 400
- * AC inlet valve 1 way = 650
- * AC inlet valve 2 way = 850
- * Pressure sensor with pipe = 950
- * DC inlet valve 1 way = 900

* DC inlet valve 2 way	= 1150
* Hall sensor	= 1000
* Direct drive motor	= 3500
* Motor universal	= 3800
* V Belt	= 850

Front Load - Noise Issue

* Shocker 2 piece	= 1800
* Drum Bering/oil seal with cleaning	= 2200

Front Load - Spin Issue

* Drain pump motor	= 1450
* Assembly drain pump	= 1500
* Drain pump motor (Double way)	= 2200

Front Load - Water Leakage

* Drain cleaning	= 300
* Drain rubber hose	= 500

Front Load - Accessories

* Chemical wash (front load)	= 1500
* Front load trolley stand	= 1200
* Extension inlet pipe 4 meter (with adaptor)	= 600
* Drain pipe	= 300
* Inlet pipe 1.5 mtr with adaptor	= 400
* Tap adaptor	= 400
* Power cord	= 350
* Door gasket	= 2000
* Front load cover	= 700

Front Load - Installation

* Installation/uninstallation	= 400
-------------------------------	-------